

VEHICLE INSPECTION REPORT

RV16LFG

Mini Countryman 1.6 Cooper S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	31/05/2016	Colour	WHITE	MOT Due	11/09/2027
Year	2016	VIN	WMWZC32070WT44674	Gearbox	MANUAL
Mileage	48,809 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	PETROL	Keys	2	Doors	5

Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	6.0mm


Spare

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5




3: Wheel nsf
Scratched
Over 50mm



4: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Dented
Between 10mm + 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Chipped
1 To 5




10: Wheel osr
Scratched
Over 50mm



11: Door osr
Dented
Between 10mm + 30mm



12: Door osf
Chipped
Edge Chip




13: Bonnet
Dented
Between 10mm + 30mm



14: Wheel osf
Scratched
Over 50mm



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
1 To 5



17: Seat Base Cover of
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		