

VEHICLE INSPECTION REPORT

HY66HYM

Nissan Qashqai 1.5 dCi Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	30/09/2016	Colour	RED	MOT Due	08/10/2026
Year	2016	VIN	SJNFAAJ11U1795233	Gearbox	MANUAL
Mileage	59,536 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	DIESEL	Keys	1	Doors	5

Light on dash relating to suspected water in fuel, fuel filter possibly needs changing or a sensor issue

Tyres

NSF	YOKOHAMA	5.0mm
NSR	PACE	6.0mm
OSF	YOKOHAMA	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Dented
Over 30mm



3: Door osf
Dented
Over 30mm



4: Wheel osr
Corroded
Light




5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel nsr
Corroded
Light



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Chipped
1 To 5



10: Door nsr
Chipped
Edge Chip



11: Door nsf
Chipped
1 To 5



12: Door nsf
Chipped
Edge Chip



13: Wing nsf
Chipped
1 To 5



14: Wheel nsf
Corroded
Light



15: Wing nsf
Scratched
UpTo 25mm Thru Paint

16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		