



VEHICLE INSPECTION REPORT

MJ70RDV

Land Rover Discovery 2.0 SD4 S Commercial Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/10/2020	Body Style	Light 4X4 Utility	Last service miles	74,867
Year	2020	Keys	1	MOT Due	17/02/2027
Mileage	75,789 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	8
Colour	BLACK	Number of stamps	5	Doors	5
VIN	SALRACAN0L2443766	Last service date	14/02/2026		

Last Service - 14.02.26 at 74867 miles (5 services) Engine knocking
Eml light is on car been plugged in and detected cylinder 1 contribution/ balance fault

Tyres


NSF	MICHELIN	6.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	6.0mm
OSR	MICHELIN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Metallic Paint
- Leather seat trim
- Cruise control
- Digital radio
- Drivers airbag
- Front parking sensor
- Air conditioning
- Passenger airbag
- Park assist camera
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Chipped
1 To 5



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: A Post ns
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint




7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



11: Tailgate
Poor Previous Repair
Poor Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
Chipped
Edge Chip



16: Wing osf
Chipped
1 To 5



17: Roof
Scratched
Over 25mm Thru Paint



18: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK