

VEHICLE INSPECTION REPORT

BJ66EGX

Nissan Juke 1.6 Tekna 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	30/09/2016	Colour	GREY	MOT Due	29/09/2027
Year	2016	VIN	SJNFBAF15U7273609	Gearbox	CVT
Mileage	38,485 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	PETROL	Keys	2	Doors	5


Tyres

NSF	GT RADIAL	5.0mm
NSR	PIRELLI	Damaged
OSF	GT RADIAL	5.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Fascia Trim
Damaged
Replace



2: Seat Back Cover osf
Scuffed
Over 25mm



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint




7: Wing nsf
Dented
2 Or Less UpTo 10mm



8: Door nsf
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
Up To 25mm Thru Paint



12: Bumper Rear Moulding
Missing
Replace



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel osr
Chipped
1 To 5



15: Door osr
Chipped
Edge Chip



16: Door osr
Chipped
1 To 5



17: Door osf
Chipped
Edge Chip



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Tyre nsr
Damaged
Replace



21: Qtr Panel osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK