



VEHICLE INSPECTION REPORT

GP17BZB

Honda HR-V 1.6 i-DTEC SE Navi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
4

Details

Reg. date	08/08/2017	Colour	RED	MOT Due	15/08/2027
Year	2017	VIN	3HGRU8750HM300751	Gearbox	MANUAL
Mileage	56,970 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	DIESEL	Keys	1	Doors	5


Tyres

NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Front parking sensor
- Rear parking sensor

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Other
N/A
N/A




5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm




9: Wing osf
Chipped
1 To 5



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Tailgate
Scratched
Up To 25mm Thru Paint




14: Wheel osr
Scratched
Over 50mm



15: Bumper Rear
Poor Previous Repair
Poor Paint




16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Chipped
1 To 5



18: Door osf
Dented
With Paint Damage



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Roof
Scratched
Over 25mm Thru Paint



21: A Post os
Dented
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK