



VEHICLE INSPECTION REPORT

GX23YBG

Audi Q3 35 TDI Black Edition 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	03/03/2023	Colour	GREY	MOT Due	02/03/2027
Year	2023	VIN	WAUZZZF3XP1088429	Gearbox	SEMI AUTO
Mileage	86,753 Miles Warranted	Body Style	Estate	Gears	7
Fuel Type	DIESEL	Keys	2	Doors	5


Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Up To 50mm



5: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



6: Wheel nsr
Corroded
Light



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Door osr
Chipped
Edge Chip



9: Door osf
Chipped
Edge Chip



10: Wing osf
Scratched
Over 25mm Thru Paint



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No