

VEHICLE INSPECTION REPORT

KW15EVH

Citroen Grand C4 Picasso 2.0 BlueHDi Exclusive 5dr EAT6

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
4

Details

Reg. date	02/06/2015	Colour	BLUE	MOT Due	17/11/2026
Year	2015	VIN	VF73AAHXTFJ626014	Gearbox	AUTOMATIC
Mileage	66,989 Miles Warranted	Body Style	MPV	Gears	6
Fuel Type	DIESEL	Keys	1	Doors	5

Tyres


NSF	AUTOGREEN	5.0mm
NSR	AUTOGREEN	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	FIRESTONE	5.0mm

Spare

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Headrest Assy Rear Seat ns
Missing
Replace



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
1 To 5



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Wheel nsf
Scratched
Over 50mm



6: A Post nsf
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Door nsf
Poor Previous Repair
Poor Paint



9: Wing nsf
Poor Previous Repair
Poor Paint



10: Door nsr
Dented
Over 30mm




11: Wheel osr
Scratched
Up To 50mm



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Tailgate
Dented
Between 10mm + 30mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Poor Previous Repair
Rippled UpTo 30%



16: Door osf
Chipped
Edge Chip



17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Bumper Front
Insecure
Action Required

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK