



VEHICLE INSPECTION REPORT

LP66KLM

Mercedes-Benz B Class B180d AMG Line 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	30/01/2017	Body Style	MPV	Last service miles	5,887
Year	2017	Keys	2	MOT Due	23/11/2026
Mileage	42,590 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	4	Doors	5
VIN	WDD2462122N191167	Last service date	26/11/2020		

LAST SERVICE 26/11/2020 @ 5,887 MILES (4 SERVICES) Bonnet catch broken

Tyres

NSF	SUNNY	3.0mm
NSR	KINGSTAR	3.0mm
OSF	SUNNY	3.0mm
OSR	KINGSTAR	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Seat Base Cover osr
Holed
Over 3mm



2: Wheel osf
Corroded
Light



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Corroded
Light



7: Bumper Rear
Chipped
Multiple Chips



8: Qtr Panel nsr
Chipped
1 To 5



9: Wheel nsr
Corroded
Light



10: Door nsr
Chipped
1 To 5



11: Wheel nsf
Corroded
Light



12: Bumper Front
Poor Previous Repair
Paint Flake

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK