



VEHICLE INSPECTION REPORT

LY18ZTH

Audi A3 1.5 TFSI Sport 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/03/2018	Body Style	Convertible	Last service miles	38,103
Year	2018	Keys	2	MOT Due	23/03/2027
Mileage	38,812 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	6	Doors	2
VIN	WAUZZZ8V0J1055106	Last service date	12/03/2026		

£90 ADDITIONAL FEE

LAST SERVICE 12/03/2026 @ 38,103 MILES (6 SERVICES, 4 MAIN DEALER) Front brakes clicking

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos






Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm




2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Poor Previous Repair
Paint Flake



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Tailgate
Poor Previous Repair
Poor Paint



7: Qtr Panel nsr
Dented
With Paint Damage




8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Scratched
Over 25mm Thru Paint




10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		