



VEHICLE INSPECTION REPORT

LX21UOK

Audi A1 25 TFSI Technik 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/03/2021	Body Style	Hatchback	Last service miles	36,267
Year	2021	Keys	2	MOT Due	17/02/2027
Mileage	56,700 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	2	Doors	5
VIN	WAUZZZGB0MR035791	Last service date	19/04/2023		

£90 ADDITIONAL FEE

LAST SERVICE 19/04/2023 @ 36,267 MILES (2 SERVICES, BOTH MAIN DEALER)

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Alarm
- Cloth seat trim
- Cruise control
- Trip computer
- Electric door mirrors
- Rear electric windows
- 3x3 point rear seat belts
- Side airbags
- Central locking
- Alloy wheels
- PAS
- Digital radio
- Xenon headlights
- Rear headrests
- ABS
- Traction control
- Immobiliser
- Rear wiper
- Mobile phone App interface
- Air conditioning
- Steering wheel rake adjustment
- Drivers airbag
- Tyre pressure monitor
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Poor Previous Repair
Poor Paint



4: Qtr Panel osr
Poor Previous Repair
Poor Paint



5: Bumper Rear
Cracked
Over 25mm



6: Bumper Rear Moulding
Broken
Replace



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint



8: Door nsr
Dented
With Paint Damage



9: Door nsf
Dented
With Paint Damage



10: Wing nsf
Poor Previous Repair
Poor Paint



11: Wheel nsf
Scratched
Up To 50mm



12: Bumper Front
Poor Previous Repair
Poor Paint



13: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK