



VEHICLE INSPECTION REPORT

VO21ZGR

Volkswagen Arteon 2.0 TSI R-Line 5dr DSG

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	09/06/2021	Body Style	Hatchback	Last service miles	49,129
Year	2021	Keys	2	MOT Due	01/03/2027
Mileage	52,701 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WVWZZZ3HZME001319	Last service date	10/02/2026		

£90 ADDITIONAL FEE

Last service 10/02/2026 at 49,129 miles- 6 main dealer services Sos light on

Tyres

NSF	FALKEN	4.0mm
NSR	FALKEN	4.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Reverse parking aid
- Digital radio
- Electric sunroof
- Climate control
- Cruise control
- Park assist camera
- Service indicator
- USB/iPod interface
- Front fog lights
- Electrically adjustable drivers seat
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Body coloured bumpers
- Xenon headlights
- Electrically adjustable passenger seat
- Heated front seat
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Air conditioning
- Folding rear seats
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- Drivers airbag
- Traction control
- Immobiliser
- Front electric windows
- Rear armrest
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Remote central locking
- Front head restraints
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Alarm
- Leather seat trim
- Height adjustable drivers seat
- Rear headrests
- ABS
- Side airbags
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Qtr Panel osr
Chipped
1 To 5



4: Bumper Rear
Chipped
1 To 5



5: Door nsr
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Bonnet
Dented
With Paint Damage



8: Seat Back Cover osf
Scuffed
UpTo 25mm



9: Bumper Front
 Scratched
 Over 100mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		