



VEHICLE INSPECTION REPORT

GV68FNNH

Mercedes-Benz C Class C200 Sport Premium 4dr 9G-Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	26/09/2018	Body Style	Saloon	MOT Due	13/12/2026
Year	2018	Keys	2	Gearbox	AUTOMATIC
Mileage	27,193 Miles Warranted	Service history	Yes	Gears	9
Fuel Type	PETROL	Service documents	Printout	Doors	4
Colour	SILVER	Number of stamps	2		
VIN	WDD2050772R426936	Last service date	04/08/2025		

Last Service - 04.08.2025 at unnown miles (2 services)

Tyres		
NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Wheel osr
Corroded
Light



5: Bumper Rear
Chipped
Multiple Chips



6: Tailgate
Dented
2 Or Less UpTo 10mm




7: Wheel nsr
Corroded
Light



8: Door nsf
Chipped
Edge Chip



9: Wheel nsf
Corroded
Light



10: Bumper Front
Scratched
UpTo 25mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: A Post os
Chipped
1 To 5

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK