



VEHICLE INSPECTION REPORT

LT18GJV

Mitsubishi Outlander 2.2 DI-D 3 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/07/2018	Body Style	Estate	MOT Due	14/04/2027
Year	2018	Service history	Yes	Gearbox	AUTOMATIC
Mileage	92,529 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	DIESEL	Number of stamps	8	Doors	5
Colour	BROWN	Last service date	06/08/2025		
VIN	JMAXLGF6WJJ400133	Last service miles	77,874		

Last Service - 06.08.2025 at 77874 miles (8 Services)

Tyres



NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Climate control
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Rear airbags
- Alarm
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- PAS
- Radio/CD
- Roof rails
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Dented
2 Or Less UpTo 10mm



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Qtr Panel Trim ns
Broken
Replace



5: Door nsr
Chipped
1 To 5




6: Door nsf
Chipped
1 To 5



7: Door nsf
Dented
2 Or Less UpTo 10mm




8: Wheel nsf
Scratched
Over 50mm




9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Bonnet
Chipped
1 To 5



11: Screen Front
Chipped
UpTo 10mm



12: Door osr
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK