



VEHICLE INSPECTION REPORT

ST20TCV

Jaguar E-Pace 2.0d S 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/03/2020	Keys	2	CAP Clean	£4,500.00
Year	2020	Service history	Yes	CAP Average	£3,900.00
Mileage	90,568 Miles Warranted	Service documents	Printout	CAP Below	£3,300.00
Fuel Type	DIESEL	Number of stamps	5	Gearbox	MANUAL
Colour	GREY	Last service date	20/06/2026	Gears	6
VIN	SADFB2CN4L1004594	Last service miles	86,385	Doors	5
Body Style	Estate	MOT Due	03/03/2027		

Last Service - 20.06.2026 at 86385 miles (5 Services)
Timing Chain Replaced 20.06.2026 @ 86385 Miles

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	3.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- | | | | |
|---|---|---|---|
| <ul style="list-style-type: none">• Bluetooth connection• Navigation system• Telephone• Air conditioning | <ul style="list-style-type: none">• Cruise control• Park assist camera• Radio/CD• Climate control | <ul style="list-style-type: none">• Front parking sensor• Rear parking sensor• Body coloured bumpers• Electrically adjustable drivers seat | <ul style="list-style-type: none">• Heated front seat• Rear wiper• Electric door mirrors• Electrically adjustable passenger seat |
| <ul style="list-style-type: none">• Front armrest• Metallic Paint• Traction control• Leather seat trim | <ul style="list-style-type: none">• Front electric windows• ABS• Tyre pressure monitor• Alloy wheels | <ul style="list-style-type: none">• Rear electric windows• Drivers airbag• Central locking | <ul style="list-style-type: none">• Rear headrests• Passenger airbag• Remote central locking |

Photos





Condition Check



Damage Photos



1: Door osf
Dented
Over 30mm



2: Door osr
Chipped
1 To 5



3: Wheel osr
Scratched
Up To 50mm



4: Door nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK