



VEHICLE INSPECTION REPORT

KX68GKJ

Volkswagen Golf 1.0 TSI 110 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/12/2018	Body Style	Hatchback	Last service miles	46,478
Year	2018	Keys	2	MOT Due	05/12/2026
Mileage	51,610 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	3	Doors	5
VIN	WVWZZZAUZKW007490	Last service date	03/12/2025		

Last Service - 03.12.2025 at 46478 miles (3 Services)


Tyres

NSF	INFINITY	4.0mm
NSR	OVATION	4.0mm
OSF	INFINITY	4.0mm
OSR	OVATION	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Chipped
1 To 5



3: Bumper Rear
Chipped
1 To 5



4: Door nsr
Chipped
1 To 5




5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Chipped
Edge Chip



7: Wing nsf
Chipped
1 To 5



8: Bumper Front
Chipped
Multiple Chips



9: Bonnet
Chipped
1 To 5

10: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK