



VEHICLE INSPECTION REPORT

HF64KVV

Honda Jazz 1.4 i-VTEC ES Plus 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	09/09/2014	Body Style	Hatchback	Last service miles	35,923
Year	2014	Keys	2	MOT Due	08/09/2027
Mileage	39,871 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	PETROL	Service documents	Service Book	Gears	1
Colour	GREY	Number of stamps	10	Doors	5
VIN	SHHGG6860EU018805	Last service date	29/08/2025		

£90 ADDITIONAL FEE

Last Service - 29.08.25 at 35923 miles (10 services)

Tyres

NSF	TOYO	5.0mm
NSR	TOYO	5.0mm
OSF	TOYO	5.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osr
Chipped
Edge Chip



3: Door osr
Dented
Between 10mm + 30mm



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Chipped
Multiple Chips



6: Tailgate
Dented
Over 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Wing nsf
Scratched
UpTo 25mm Thru Paint




10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Other
N/A
N/A



13: Bonnet
Poor Previous Repair
Poor Paint



14: Roof
Poor Previous Repair
Poor Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK