



VEHICLE INSPECTION REPORT

GX23PXE

Mercedes-Benz GLS GLS 400d 4Matic Night Ed 5dr 9G-Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	08/03/2023	Body Style	Estate	Last service miles	10,680
Year	2023	Keys	2	MOT Due	17/08/2027
Mileage	52,442 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	9
Colour	GREY	Number of stamps	1	Doors	5
VIN	W1NFF2DE5PA891541	Last service date	26/02/2024		

£90 ADDITIONAL FEE

Last Service - 26.02.2024 at 10680 miles (1 main dealer Services)

Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	5.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking


Photos







Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Door Mirror Assy osf
Broken
Replace



4: Door osf
Dented
Between 10mm + 30mm



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Chipped
Multiple Chips



8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Chipped
1 To 5



10: Door nsr
Dented
With Paint Damage



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Chipped
Multiple Chips



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		