



VEHICLE INSPECTION REPORT

YB10WZW

BMW X1 sDrive 18d SE 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 19/07/2010

Year 2010

Mileage 159,639 Miles
Warranted

Fuel Type Diesel

Colour BLACK

VIN WBAVN12070VM53381

Body Style Estate

Keys 1

MOT Due 19/12/2025

Gearbox MANUAL

Gears 6

Code 218 on dash

Tyres

NSF BUDGET 3.0mm

NSR BUDGET 3.0mm

OSF BUDGET 3.0mm

OSR BUDGET 3.0mm


Spare

Features


- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Bumper Rear
Poor Previous Repair
Poor Paint



14: Boot Lid
Chipped
1 To 5



15: Qtr Panel osr
Chipped
1 To 5



16: Door osr
Dented
Over 30mm



17: Door osf
Dented
Between 10mm + 30mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Wheel osr
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK