



VEHICLE INSPECTION REPORT

GV69GYK

Citroen C3 Aircross 1.2 PureTech 110 Flair 5dr [6 speed]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/11/2019	Body Style	MPV	Last service miles	72,691
Year	2019	Keys	2	MOT Due	19/12/2026
Mileage	84,801 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	3	Doors	5
VIN	VF72RHNPMK4499015	Last service date	08/12/2025		

Last Service - 08.12.2025 at 72691 miles (3 Services) Car hunting


Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light




2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5




4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Corroded
Light



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Corroded
Light



9: Door nsr
Chipped
1 To 5




10: Door nsr
Scratched
UpTo 25mm Thru Paint



11: Door nsf
Scratched
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK