



VEHICLE INSPECTION REPORT

GY16BBZ

Nissan Pulsar 1.2 DiG-T Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2016	Body Style	Hatchback	Last service miles	68,036
Year	2016	Keys	2	MOT Due	30/03/2027
Mileage	80,786 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	5	Doors	5
VIN	VSKDDAC13U0069069	Last service date	14/03/2025		

£90 ADDITIONAL FEE

Last Service - 14.03.2025 at 68036 miles (5 Services)

Tyres



NSF	BUDGET	2.0mm
NSR	HANKOOK	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wheel osr
Corroded
Light




3: Wheel nsr
Corroded
Light




4: Wheel nsf
Corroded
Light



5: Wing osf
Chipped
1 To 5



6: Door osf
Chipped
1 To 5



7: Door osr
Chipped
1 To 5



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Door nsr
Dented
With Paint Damage



12: Door nsf
Dented
Over 30% Of Panel



13: Wing nsf
Poor Previous Repair
Poor Paint



14: Bumper Front
Poor Previous Repair
Poor Paint



15: Bonnet
 Poor Previous Repair
 Paint Flake

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK