



VEHICLE INSPECTION REPORT

GF62LNK

Mini Hatchback 1.6 Cooper 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/10/2012	Keys	1	CAP Clean	£1,500.00
Year	2012	Service history	Yes	CAP Average	£1,100.00
Mileage	76,807 Miles Warranted	Service documents	Electronic / Online	CAP Below	£700.00
Fuel Type	PETROL	Number of stamps	1	Gearbox	MANUAL
Colour	SILVER	Last service date	18/10/2014	Gears	6
VIN	WMWSU32080T528862	Last service miles	6,151	Doors	3
Body Style	Hatchback	MOT Due	31/10/2026		

£90 ADDITIONAL FEE

LAST SERVICE 18/10/2014 @ 6,151 MILES (1 SERVICE, CONFIRMED BY GROUP 1 BMW & MINI) Engine rattle
Misfires on idle
Oil light on

Tyres

NSF	BUDGET	Damaged
NSR	FIRESTONE	3.0mm
OSF	NEXEN	4.0mm
OSR	FIRESTONE	3.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Door osf
Dented
With Paint Damage




2: Qtr Panel osr
Dented
With Paint Damage




3: Wheel osr
Scratched
Over 50mm




4: Bumper Rear
Scratched
Over 100mm Thru Paint



5: Wheel nsr
Corroded
Light



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsf
Chipped
1 To 5




8: Door nsf
Chipped
Edge Chip



9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Roof
Chipped
1 To 5



12: Bonnet
Chipped
1 To 5



13: Tyre nsf
Damaged
Replace



14: Aerial
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK