



VEHICLE INSPECTION REPORT

GJ14XTP

Audi A6 2.0 TDI SE 4dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	31/03/2014	Body Style	Saloon	Last service miles	89,221
Year	2014	Keys	2	MOT Due	08/02/2027
Mileage	133,767 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6	Doors	4
VIN	WAUZZZ4G2EN121208	Last service date	03/03/2023		

£100 ADDITIONAL FEE

LAST SERVICE 03/03/2023 @ 89,221 MILES (6 SERVICES)

Tyres

NSF	ROADSTONE	3.0mm
NSR	ROADSTONE	3.0mm
OSF	ROADSTONE	3.0mm
OSR	MAXXIS	4.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos



Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Wing osf
Poor Previous Repair
Paint Flake



3: Door Mirror Assy osf
Broken
Replace



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Poor Previous Repair
Paint Flake



7: Wheel osr
Scratched
Up To 50mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5



10: Door nsr
Scratched
Over 25mm Thru Paint




11: Door nsf
Dented
With Paint Damage




12: Wing nsf
Scratched
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK