



VEHICLE INSPECTION REPORT

RO60YSV

BMW 3 Series 318i Exclusive Edition 4dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/10/2010	Body Style	Saloon	Last service miles	109,007
Year	2010	Keys	2	MOT Due	26/08/2027
Mileage	115,655 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	8	Doors	4
VIN	WBAPF52070A921940	Last service date	03/05/2025		

£90 ADDITIONAL FEE

COOLANT PUMP REPLACED 21/10/2025

LAST SERVICE 03/05/2025 @ 109,007 MILES (8 SERVICES)

Radio missing

EML light on car has been plugged in and detects pre catalyst oxygen o2 sensor line fault on bank 1

Post catalyst fuel trim via oxygen sensor system too Rich bank 1

System too lean bank 1

Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Heated front seat
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Tailgate
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Up To 50mm



11: Door nsr
Chipped
Multiple Chips



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Poor Previous Repair
Poor Paint



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Door Pad nsf
Scuffed
Over 25mm



18: Wing osf
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK