



VEHICLE INSPECTION REPORT

YD71RCV

Nissan Navara Double Cab Pick Up N-Guard 2.3dCi 190 TT 4WD Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Photocopy



Details

Reg. date	30/11/2021	Body Style	Pick-up	Last service miles	55,122
Year	2021	Keys	1	MOT Due	29/11/2026
Mileage	61,662 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	3		
VIN	VSKCTND23U0174667	Last service date	15/11/2025		

LAST SERVICE 15/11/2025 @ 55,122 MILES (3 SERVICES)

Tyres

NSF	WESTLAKE	Damaged
NSR	WESTLAKE	3.0mm
OSF	WESTLAKE	4.0mm
OSR	WESTLAKE	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Air conditioning
- Drivers airbag
- Leather seat trim
- Cruise control
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Heated front seat
- Radio/CD
- Rear electric windows
- Central locking
- Navigation system
- Electric sunroof
- Metallic Paint
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osr
Chipped
1 To 5



2: Door osr
Chipped
Edge Chip



3: Qtr Panel osr
Chipped
1 To 5



4: Fuel Flap
Missing
Replace



5: Qtr Panel nsr
Dented
Between 10mm + 30mm



6: Door nsf
Dented
Over 30mm



7: Wing nsf
Dented
Over 30mm



8: Bonnet
Chipped
1 To 5



9: Roof
Chipped
1 To 5

10: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		