



VEHICLE INSPECTION REPORT

LP16JZV

Mercedes-Benz C Class C220d SE Executive 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/05/2016	Body Style	Estate	Last service miles	92,910
Year	2016	Keys	2	MOT Due	22/10/2027
Mileage	106,000 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	8	Doors	5
VIN	WDD2052042F261482	Last service date	26/03/2025		

£90 ADDITIONAL FEE

Last Service - 26.03.2025 at 92910 miles (8 services)

Intermittent engine knock

Tyres

NSF	KUMHO	5.0mm
NSR	FARROAD	5.0mm
OSF	KUMHO	5.0mm
OSR	FARROAD	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Reverse parking aid
- Digital radio
- Space saver spare wheel
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- Curtain airbags
- Traction control
- Immobiliser
- Spare wheel
- Cruise control
- PAS
- Service indicator
- USB/iPod interface
- Xenon headlights
- Electrically adjustable passenger seat
- Rear armrest
- Solid Paint
- Drivers airbag
- Tyre pressure monitor
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Steering wheel mounted controls
- Body coloured bumpers
- Air conditioning
- Folding rear seats
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Alarm
- Leather seat trim
- Navigation system
- Rear wiper
- Trip computer
- Electric door mirrors
- Climate control
- Front electric windows
- Rear headrests
- ABS
- Rear airbags
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Other
N/A
N/A



3: Wheel osf
Scratched
Over 50mm



4: Wing osf
Poor Previous Repair
Poor Paint



5: Door osf
Chipped
1 To 5



6: Door osf
Chipped
Edge Chip




7: Door osr
Chipped
1 To 5



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Wheel nsr
Scratched
Up To 50mm



12: Door nsr
Chipped
1 To 5



13: Wing nsf
Scratched
Up To 25mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Poor Previous Repair
Poor Paint



16: Bonnet
Chipped
Multiple Chips



17: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK