



VEHICLE INSPECTION REPORT

WN18EXU

Audi A4 2.0T FSI S Line 4dr S Tronic [Leather/Alc]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/03/2018	Body Style	Saloon	Last service miles	59,965
Year	2018	Keys	2	MOT Due	23/03/2027
Mileage	72,003 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	6	Doors	4
VIN	WAUZZZF46JA147427	Last service date	04/11/2024		

£100 ADDITIONAL FEE

Last Service - 04.11.24 @ 59965 miles (6 main dealer services)

Tyres

NSF	DAVANTI	Damaged
NSR	CONTINENTAL	5.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: A Post ns
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Edge Chip



8: Door nsf
Chipped
1 To 5



9: Door nsr
Chipped
Edge Chip



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Boot Lid
Chipped
1 To 5



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



16: Door osf
Chipped
Edge Chip



17: Wheel osf
Scratched
Over 50mm



18: A Post os
Scratched
Over 25mm Thru Paint



19: Tyre nsf
Damaged
Replace



20: Door Pad osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK