



VEHICLE INSPECTION REPORT

BK70ARF

Ford Transit 2.0 EcoBlue 105ps H2 Leader Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/09/2020	Keys	2	CAP Clean	£8,100.00
Year	2020	Service history	Yes	CAP Average	£7,100.00
Mileage	75,400 Miles Warranted	Service documents	Printout	CAP Below	£5,700.00
Fuel Type	DIESEL	Number of stamps	1	Gearbox	MANUAL
Colour	WHITE	Last service date	03/08/2026	Gears	6
VIN	WF0EXXTTREL39425	Last service miles	73,122		
Body Style	Panel Van	MOT Due	Expired		

£100 ADDITIONAL FEE

Last Service - 03.08.26 at 73122 miles (1 services)

Wetbelt replaced 03.08.26 @ 73122 miles

MOT EXPIRED Light missing cover on the roof

Tyres

NSF	BUDGET	5.0mm
NSR	HIFLY	6.0mm
OSF	HIFLY	6.0mm
OSR	HIFLY	6.0mm
Spare		

Features


- Bluetooth connection
- Drivers airbag
- Media storage
- Central locking
- Front electric windows
- Cloth seat trim
- Metallic Paint

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Chipped
1 To 5



3: Front TowEye Cvr
Missing
Replace



4: Bumper Front
Dented
Over 30mm



5: Fog Lamp Surround ns
Missing
Replace



6: Flasher Side Repeater ns
Broken
Replace



7: Wing nsf
Chipped
1 To 5



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsf
Chipped
Edge Chip



10: Door nsr
Dented
With Paint Damage



11: Sill Panel Trim ns
Broken
Replace



12: Qtr Panel nsr
Dented
Over 30mm



13: Tailgate
Cracked
Replace



14: Roof
Dented
With Paint Damage



15: Qtr Panel osr
Dented
Over 30mm



16: Panel Front
Dented
Between 10mm + 30mm



17: Door osf
Dented
With Paint Damage



18: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK