



VEHICLE INSPECTION REPORT

YC59FHO

BMW 1 Series 120i M Sport 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/10/2009	Keys	2	CAP Clean	£1,725.00
Year	2009	Service history	Yes	CAP Average	£1,300.00
Mileage	100,076 Miles Warranted	Service documents	Printout	CAP Below	£900.00
Fuel Type	PETROL	Number of stamps	4	Gearbox	MANUAL
Colour	WHITE	Last service date	21/09/2017	Gears	6
VIN	WBAUC120X0VM01549	Last service miles	29,152	Doors	2
Body Style	Coupe	MOT Due	11/12/2026		

LAST SERVICE 21/09/2017 @ 29,152 MILES (4 SERVICES) Exhaust blowing
Engine tapping

Tyres


NSF	MICHELIN	3.0mm
NSR	FIREMAX	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	2.0mm
Spare		

Features


- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Leather seat trim
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Rusted
Over 5mm



2: Door osf
Dented
2 Or Less UpTo 10mm



3: Wheel osr
Scratched
Up To 50mm



4: Qtr Panel osr
Poor Previous Repair
Poor Paint



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Qtr Panel nsr
Poor Previous Repair
Poor Paint



7: Wheel nsr
Scratched
Over 50mm



8: Wing nsf
Poor Previous Repair
Paint Flake



9: Bonnet
Dented
With Paint Damage



10: Bumper Front
Chipped
Multiple Chips



11: Screen Front
Chipped
Over 10mm



12: Seat Base Cover osf
Scuffed
Over 25mm



13: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK