



VEHICLE INSPECTION REPORT

MA66WCX

Volkswagen Golf 2.0 TSI GTI 5dr [Nav]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/11/2016	Keys	2	CAP Clean	£10,250.00
Year	2016	Service history	Yes	CAP Average	£9,200.00
Mileage	58,111 Miles Warranted	Service documents	Service Book	CAP Below	£8,125.00
Fuel Type	PETROL	Number of stamps	6	Gearbox	MANUAL
Colour	GREY	Last service date	29/10/2025	Gears	6
VIN	WVWZZZAUZH020043	Last service miles	52,894	Doors	5
Body Style	Hatchback	MOT Due	15/04/2027		

LAST SERVICE 29/10/2025 @ 52,894 MILES (6 SERVICES)

Tyres

NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Poor Previous Repair
Poor Paint



3: Door osf
Poor Previous Repair
Poor Paint



4: Door osr
Poor Previous Repair
Poor Paint



5: Wheel osr
Scratched
Up To 50mm



6: Qtr Panel osr
Poor Previous Repair
Poor Paint



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
1 To 5




10: Wheel nsf
Scratched
Over 50mm



11: Wing nsf
Chipped
1 To 5



12: Bumper Front
Poor Previous Repair
Poor Paint



13: Bonnet
Poor Previous Repair
Poor Paint



14: Screen Front
Chipped
UpTo 10mm



15: Qtr Panel nsr
Poor Previous Repair
Poor Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	Fault	Steering	OK