



VEHICLE INSPECTION REPORT

RJ17LJK

BMW 5 Series 520d SE 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/06/2017	Body Style	Saloon	MOT Due	Expired
Year	2017	Keys	2	Gearbox	AUTOMATIC
Mileage	65,786 Miles Warranted	Service history	Yes	Gears	8
Fuel Type	DIESEL	Service documents	Printout	Doors	4
Colour	BLUE	Number of stamps	4		
VIN	WBAJC32040G868579	Last service date	04/11/2024		

MOT EXPIRED
SOME SERVICES ARE IN KM
LAST SERVICE 04/11/2024 @ 78,945KM (4 SERVICES)

Tyres




NSF	KUMHO	6.0mm
NSR	KUMHO	6.0mm
OSF	KUMHO	6.0mm
OSR	KUMHO	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Service indicator
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



1: Centre Console Front
Scuffed
Over 25mm




2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint




4: Wing nsf
Dented
Between 10mm + 30mm




5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 30mm




9: Bumper Rear
Scratched
25 to 100mm Thru Paint




10: Qtr Panel osr
Dented
Over 2 UpTo 10mm



11: Door osr
Chipped
Edge Chip



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Chipped
Edge Chip



14: Wing osf
Chipped
1 To 5



15: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK