



VEHICLE INSPECTION REPORT

LN16DZY

Mercedes-Benz E Class E200 AMG Line 2dr 7G-Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/03/2016	Body Style	Convertible	Last service miles	82,764
Year	2016	Keys	2	MOT Due	10/03/2027
Mileage	86,293 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	7
Colour	WHITE	Number of stamps	8	Doors	2
VIN	WDD2074342F340764	Last service date	09/03/2026		

Last Service - 09.03.2026 at 82764 miles (8 Services) Eml light is on car has been plugged in and detects cylinder 4 misfire detected

Tyres

NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Dented
Over 2 UpTo 10mm



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Door nsf
Chipped
Edge Chip



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Chipped
1 To 5



13: Roof
Chipped
1 To 5



14: Bumper Rear
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		