



VEHICLE INSPECTION REPORT

SK20TGY

BMW 2 Series 218i M Sport 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/07/2020	Body Style	Coupe	Last service miles	29,841
Year	2020	Keys	2	MOT Due	16/07/2027
Mileage	60,472 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Electronic / Online	Gears	6
Colour	WHITE	Number of stamps	2	Doors	4
VIN	WBA12AK0507F90799	Last service date	23/04/2024		

£100 ADDITIONAL FEE

Last Service - 23.04.24 @ 29841 miles (2 services)

Mileage discrepancy in service history in 2024

Tyres

NSF	ROYALBLACK	5.0mm
NSR	SAILUN	5.0mm
OSF	BUDGET	5.0mm
OSR	ROYALBLACK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Shelfload Cover Rear
Missing
Replace
Trim in boot missing




2: Bonnet
Chipped
1 To 5



3: Other
N/A
N/A
Condensation in headlight



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Chipped
1 To 5



7: Door nsr
Dented
2 Or Less UpTo 10mm



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Scratched
Over 25mm Thru Paint




11: Door osf
Chipped
Edge Chip



12: Door osf
Dented
Over 2 UpTo 10mm



13: Wing osf
Chipped
1 To 5



14: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK