



VEHICLE INSPECTION REPORT

EX66GMO

Volkswagen Polo 1.0 75 Match 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	03/09/2016	Body Style	Hatchback	Last service miles	48,978
Year	2016	Keys	2	MOT Due	Expired
Mileage	55,956 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	8	Doors	3
VIN	WVWZZZ6RZHY025631	Last service date	15/08/2024		

£65 ADDITIONAL FEE Last service 15/08/2024 @ 48978 miles (8 SERVICES 5 MAIN DEALER) Rough running and Eml on

Tyres

NSF	TOYO	4.0mm
NSR	TOYO	4.0mm
OSF	TOYO	4.0mm
OSR	TOYO	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
Dented
With Paint Damage



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Wing nsf
Chipped
1 To 5



6: Wheel nsr
Scratched
Over 50mm



7: Wheel nsf
Scratched
Over 50mm



8: Bonnet
Chipped
1 To 5



9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Wing osf
Dented
Over 30mm



11: Wheel osf
Scratched
Over 50mm



12: Door osf
Chipped
1 To 5



13: Qtr Panel osr
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK