

VEHICLE INSPECTION REPORT

GU10RUV

Audi A3 1.4 TFSI Sport 5dr S Tronic [Start Stop]

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
2

Details

Reg. date	02/03/2010	VIN	WAUZZZ8P5AA086563	CAP Average	£3,550.00
Year	2010	Body Style	Hatchback	CAP Below	£2,975.00
Mileage	40,754 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Petrol	MOT Due	02/03/2026	Gears	7
Colour	WHITE	CAP Clean	£4,175.00	Doors	5

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Remote central locking
- Rear wiper
- Air conditioning
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Rear headrests
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front armrest
- Solid Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osr
Scratched
Over 25mm Not Thru Paint



3: Wheel osr
Scratched
Over 50mm



4: Qtr Panel nsr
Dented
Over 30mm



5: Wheel nsr
Scratched
Over 50mm



6: Wheel nsf
Scratched
Over 50mm



7: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK