46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GP69LML

Audi Q3 35 TFSI S Line 5dr

nama GRADE 1

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	22/10/2019
Year	2019
Mileage	38,279 Miles Warranted
Fuel Type	PETROL
Colour	GREY
VIN	WAUZZZF31L1020997

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	6
Last service date	15/10/2025

Last service miles	32,611
MOT Due	21/10/2027
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
LAST SERVICE 15/10/2025 @ 32,611 MILES (6 SERVICES)

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim


Photos








GP69 LML




Date & time
4:45 PM
Thursday
5.11.2026


Search
Assist
Traffic


Radio · DAB/FM
Source
Heart Sussex
Pop
Heart UK
Pop
Heart Xmas
Pop
Hits Radio 00s
Pop










Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Chipped
Edge Chip



3: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK