



VEHICLE INSPECTION REPORT

HS18AMO

Ford Fiesta 1.5 EcoBoost ST-2 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	26/07/2018	VIN	WF0FXXGAHFJM43521	CAP Average	£7,750.00
Year	2018	Body Style	Hatchback	CAP Below	£6,750.00
Mileage	42,831 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	26/07/2025	Gears	6
Colour	SILVER	CAP Clean	£8,800.00	Doors	3

£65 ADDITIONAL FEE


Tyres

NSF	MICHELIN	3.0mm
NSR	MICHELIN	3.0mm
OSF	MICHELIN	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wheel osf
Scratched
Up To 50mm



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Bumper Rear
Dented
With Paint Damage



6: Door nsr
Poor Previous Repair
Poor Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Wheel osr
Scratched
Up To 50mm



9: Door nsf
Poor Previous Repair
Poor Paint

10: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK