

VEHICLE INSPECTION REPORT

PX19FGN

Ford C-Max 1.0 EcoBoost 125 Titanium 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
2

Details

Reg. date 04/04/2019

Colour BLUE

MOT Due 05/12/2025

Year 2019

VIN WF0VXXGCEVKC46469

Gearbox MANUAL

Mileage 40,727 Miles
Warranted

Body Style MPV

Gears 6

Fuel Type Petrol

Keys 2

Tyres

NSF FALKEN 3.0mm

NSR MICHELIN 2.0mm

OSF BUDGET 4.0mm


OSR MICHELIN 2.0mm

Spare

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
2 Or Less Up To 10mm



7: Door nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Chipped
Multiple Chips



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Door osr
Dented
Over 2 UpTo 10mm



14: Door osf
Chipped
1 To 5



15: Wheel of
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK