



# VEHICLE INSPECTION REPORT

**DU15RYZ**

## Inspection

Serious Damage? No

## Vehicle

VAT Margin

V5 TBC

nama  
GRADE  
3

## Details

Reg. date 03/03/2015

Colour WHITE

MOT Due 06/03/2026

Year 2015

VIN WVWZZZAUZFW226036

Gearbox SEMI AUTO

Mileage 141,534 Miles  
Warranted

Body Style Hatchback

Gears 6

Fuel Type Petrol

Keys 2

Doors 3

Error gearbox message displays on dash

## Tyres

NSF YOKOHAMA 3.0mm

NSR YOKOHAMA 3.0mm

OSF YOKOHAMA 3.0mm


OSR YOKOHAMA 5.0mm

Spare

## Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint





3: Qtr Panel osr  
Chipped  
1 To 5



4: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



5: Wheel osr  
Scratched  
Over 50mm



6: Bumper Rear  
Poor Previous Repair  
Paint Flake



7: Wheel nsr  
Scratched  
Over 50mm



8: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



9: Wheel nsf  
Scratched  
Over 50mm




10: Wing nsf  
Chipped  
1 To 5



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint



12: Bonnet  
Chipped  
Multiple Chips



13: Roof  
Chipped  
Over 5mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK