

## **VEHICLE INSPECTION REPORT**



## Renault Kangoo 1.5 dCi 86 Expression 5dr

Non Runner		Vehicle			nama
Serious Damage?	No	VAT	VAT Qualifying		In the second se
		V5	Present		
Details					
Reg. date	30/10/2010	Keys	1	CAP Clean	£1,175.00
Year	2010	Service history	Yes	CAP Average	£770.00
Mileage	109,272 Miles Warranted	Service documents	Printout	CAP Below	£375.00
		Number of stamps	1	Gearbox	MANUAL
Fuel Type	Diesel	Last service date	21/01/2020	Gears	5
Colour	BLUE	Last service miles	94,743		
VIN	VF1KW0BB544125209	MOT Due	12/11/2025		
Body Style	MPV		,, _ 0 _ 0		

#### NON RUNNER Last service 21/01/2020 @ 94743 miles (1 MAIN DEALER SERVICE) Gears are stiff Turbo fault and front bumper misaligned

Tyres			
NSF	HANKOOK	2.0mm	
NSR	HANKOOK	3.0mm	
OSF	HANKOOK	3.0mm	
OSR	BUDGET	3.0mm	
Spare			

## **Features**

- Navigation system
  Electric door mirrors
  Metallic Paint
  Central locking

- ABS Remote central locking

• Rear wiper

- Front armrest
- Radio/CD · Front electric windows
  - Drivers airbag
    Cloth seat trim
- Rear headrests
  Passenger airbag
  Steel wheels

Body coloured bumpers

### **Photos**


















## **Condition Check**



## Damage Photos






1: Carpets Front Holed Over 3mm

2: Other N/A N/A







4: Bonnet Chipped 1 To 5



# No Image

6: Bumper Front Scratched Over 25mm Not Thru Paint



7: Wing nsf Chipped 1 To 5

Scratched

25 to 100mm Thru Paint



8: Door nsf Dented Over 30mm



9: Door nsr Dented With Paint Damage



11: Boot Lid Dented Over 2 UpTo 10mm



13: Qtr Panel osr Dented With Paint Damage



10: Qtr Panel nsr Dented With Paint Damage



12: Bumper Rear Poor Previous Repair Poor Colour



14: Door osr Scratched Over 25mm Thru Paint





Average

No

15: Door osf Dented Over 30mm 16: Wing osf Chipped 1 To 5

#### Interior

Carpet Condition	Average	Upholstery Condition
Seat Condition	Average	Odour

#### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting Fault		Gearbox Static Gear Selection (engine running)	
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK