



# VEHICLE INSPECTION REPORT

**GU61ZKG**

## Hyundai I10 1.2 Classic 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	23/09/2011	Keys	3	CAP Clean	£1,375.00
Year	2011	Service history	Yes	CAP Average	£980.00
Mileage	63,194 Miles Warranted	Service documents	Printout	CAP Below	£575.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	GREY	Last service date	03/09/2024	Gears	5
VIN	MALAN51CLBM961429	Last service miles	60,483	Doors	5
Body Style	Hatchback	MOT Due	23/09/2025		

Last Service - 03.09.2024 at 60483 miles (12 services)


### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	HANKOOK	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- PAS
- Air conditioning
- Rear headrests
- Passenger airbag
- Steel wheels
- Rear wiper
- Climate control
- Metallic Paint
- Central locking
- Radio/CD
- Front electric windows
- 3x3 point rear seat belts
- Remote central locking
- Body coloured bumpers
- Front head restraints
- Isofix child seat anchor points
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint






3: Qtr Panel osr  
Dented  
Over 30mm



4: Door osr  
Dented  
Over 2 UpTo 10mm



5: Door osr  
Scratched  
Over 25mm Not Thru Paint



6: Door osf  
Chipped  
1 To 5




7: Wing osf  
Scratched  
Over 25mm Not Thru Paint




8: Bonnet  
Chipped  
1 To 5



9: Bumper Front  
Scratched  
25 to 100mm Thru Paint



10: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



11: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



12: Door nsf  
Chipped  
1 To 5



13: Door nsf  
Dented  
Over 2 UpTo 10mm



14: Door nsr  
Dented  
Over 30mm





15: Qtr Panel nsr  
Dented  
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK