

# VEHICLE INSPECTION REPORT

**GU12YSL**

## Kia Picanto 1.0 1 3dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

### Details

Reg. date	30/03/2012	Body Style	Hatchback	CAP Clean	£1,100.00
Year	2012	Keys	1	CAP Average	£710.00
Mileage	114,021 Miles Warranted	Number of stamps	8	CAP Below	£325.00
Fuel Type	Petrol	Last service date	12/05/2020	Gearbox	MANUAL
Colour	WHITE	Last service miles	80,010	Gears	5
VIN	KNABE311LCT244267	MOT Due	19/07/2025	Doors	3

Last Service: 12/05/2020 at 80010 miles. (8 services )

### Tyres

NSF	MATADOR	3.0mm
NSR	BUDGET	Illegal
OSF	BUDGET	3.0mm
OSR	RAPID	2.0mm
Spare		

## Features


- Rear wiper
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Solid Paint
- Traction control
- Steel wheels
- Body coloured bumpers
- ABS
- Central locking
- Front electric windows
- Drivers airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Carpets Front  
Holed  
Over 3mm



2: Bonnet  
Chipped  
1 To 5






3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Chipped  
1 To 5



6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint

No Image

9: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



10: Qtr Panel osr  
Chipped  
1 To 5



11: Door osf  
Chipped  
1 To 5

No Image

12: Door osf  
Scratched  
Over 25mm Not Thru Paint



13: Wing osf  
Dented  
With Paint Damage

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK