



# VEHICLE INSPECTION REPORT

**VE58ERZ**

## Inspection

Serious Damage? No

## Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

## Details

Reg. date 29/01/2009

Year 2009

Mileage 118,567 Miles  
Warranted

Fuel Type Petrol

Colour BLACK

VIN WVVZZZ13Z9V012078

Body Style Coupe

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 10

Last service date 05/02/2024

Last service miles 109,995

MOT Due 29/01/2026

CAP Clean £1,925.00

CAP Average £1,475.00

CAP Below £1,050.00

Gearbox MANUAL

Gears 6

£100 ADDITIONAL FEE Last service 05/02/2024 @ 109995 miles (10 SERVICES 3 MAIN DEALER) book + print

## Tyres

NSF BUDGET 3.0mm

NSR ACCELERA 5.0mm

OSF BUDGET 3.0mm

OSR BUDGET 5.0mm

Spare

## Features


- Bluetooth connection
- Body coloured bumpers
- Front armrest
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Radio/CD
- Climate control
- ABS
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Dented  
With Paint Damage



2: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Over 30mm



5: Wing nsf  
Dented  
2 Or Less UpTo 10mm



6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Wheel nsf  
Scratched  
Over 50mm



8: Bumper Front  
Scratched  
Over 100mm Thru Paint



9: Bonnet  
Rusted  
Over 5mm



10: Door osf  
Dented  
Over 2 UpTo 10mm



11: Door osf  
Scratched  
Over 25mm Not Thru Paint



12: Qtr Panel osf  
Scratched  
Over 25mm Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK