

VEHICLE INSPECTION REPORT

GY72ZTJ

MG Mg Hs EXCLUSIVE

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Buyer To Apply	•	
Details					
Reg. date	15/11/2022	VIN	LSJA24U97NN179659	CAP Average	£12,350.00
Year	2022	Body Style	Estate	CAP Below	£11,100.00
Mileage	14,385 Miles Warranted	Keys	2	Gearbox	MANUAL
		MOT Due	14/11/2025	Gears	6
Fuel Type	Petrol	CAP Clean	£13,600.00		
Colour	RILIE		,	•	

£65 ADDITIONAL FEE NO V5 NO MOTS YET

-				
ı	У	r	е	s

NSF	MICHELIN	4.0mm	
NSR	MICHELIN	4.0mm	
OSF	MICHELIN	4.0mm	
OSR	MICHELIN	4.0mm	
Spare		,	

Features

- Rear electric windowsDrivers airbagRemote central locking

- Bluetooth connection
 Rear wiper
 Electric door mirrors
 Electric ally adjustable drivers seat
 Navigation system
 Telephone
 Electric sunroof
 Air conditioning
 Front armrest seat
 - Rear headrests

 - Passenger airbagLeather seat trim

- Solid Paint
- Traction controlAlloy wheels

- Rear parking sensor
 Body coloured bumpers
 Climate control
 Front electric windows

- ABS
- Central locking

Photos






















Condition Check




Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched Over 100mm Thru Paint




3: Wheel nsf Scratched Up To 50mm



4: Door nsf Dented 2 Or Less UpTo 10mm

No Image

5: Door nsr Scratched Over 25mm Not Thru Paint



6: Wheel nsr Scratched Over 50mm



7: Door nsr Dented 2 Or Less UpTo 10mm



8: Bumper Rear Chipped Multiple Chips

No Image

9: Boot Lid Scratched Over 25mm Not Thru Paint



11: Wheel osrScratchedUp To 50mm



13: Screen Front Chipped UpTo 10mm

Interior



10: Door osrScratchedOver 25mm Not Thru Paint

No Image

12: Door osfScratchedOver 25mm Not Thru Paint

Carpet Condition Seat Condition

Average Average **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		