



VEHICLE INSPECTION REPORT

HN16RJZ

DS Ds 3 1.2 PureTech 82 Chic 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/06/2016	Keys	2	CAP Clean	£2,600.00
Year	2016	Service history	Yes	CAP Average	£2,150.00
Mileage	91,034 Miles Warranted	Service documents	Service Book	CAP Below	£1,700.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	YELLOW	Last service date	25/04/2024	Gears	5
VIN	VF7SAHMZ6GW572713	Last service miles	79,905	Doors	3
Body Style	Hatchback	MOT Due	12/06/2026		

LAST SERVICE 25/04/24 @ 79905 MILES (8 SERVICES 7 MAIN DEALER) BOOK & PRINT SERVICE LIGHT ON

Tyres


NSF	GOODYEAR	3.0mm
NSR	BUDGET	4.0mm
OSF	CONTINENTAL	2.0mm
OSR	BUDGET	4.0mm
Spare		

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Scratched
UpTo 25mm Thru Paint



4: Qtr Panel osr
Chipped
1 To 5



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Wheel osr
Scratched
Over 50mm



7: Door osf
Chipped
1 To 5




8: Wheel osf
Scratched
Over 50mm



9: Wing osf
Poor Previous Repair
Poor Colour



10: Bumper Front
Poor Previous Repair
Paint Flake



11: Bonnet
Chipped
1 To 5



12: Wing nsf
Poor Previous Repair
Poor Colour



13: Wheel nsf
Scratched
Over 50mm



14: Door nsf
Dented
Over 30mm

No Image



15: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

16: Wheel nsr
Scratched
Over 50mm



17: Sill os
Poor Previous Repair
Paint Flake

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK