



VEHICLE INSPECTION REPORT

GP08BKO

Volkswagen FOX 1.2 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/06/2008	Keys	1	CAP Clean	£570.00
Year	2008	Service history	Yes	CAP Average	£200.00
Mileage	55,196 Miles Warranted	Service documents	Printout	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	BLACK	Last service date	14/06/2012	Gears	5
VIN	WVWZZZ5ZZ84157396	Last service miles	15,901	Doors	3
Body Style	Hatchback	MOT Due	Expired		

£65 ADDITIONAL FEE

Last Service - 14.06.2011 at 15901 miles (1 services)

MOT Expired Power steering heavy/power steering light on

Abs light on

Car keeps cutting out

Tyres

NSF	RAPID	4.0mm
NSR	RAPID	4.0mm
OSF	RAPID	4.0mm
OSR	RAPID	4.0mm
Spare		

Features


- Rear wiper
- Metallic Paint
- Central locking
- Radio/CD
- ABS
- Cloth seat trim
- Body coloured bumpers
- Drivers airbag
- Steel wheels
- Rear headrests
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Holed
Over 3mm



2: Bonnet
Poor Previous Repair
Paint Flake



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Dented
Over 30mm



6: Door nsf
Dented
With Paint Damage



7: Sill ns
Dented
With Paint Damage



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Boot Lid
Dented
Over 30mm



11: Qtr Panel osr
Dented
Over 30mm



12: Door osf
Dented
With Paint Damage



13: Wing osf
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	Fault