



# VEHICLE INSPECTION REPORT

**GY22CVR**

## Nissan Qashqai 1.3 DiG-T MH N-Connecta 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

### Details

Reg. date	08/04/2022	Body Style	Hatchback	CAP Below	£13,350.00
Year	2022	Keys	2	Gearbox	MANUAL
Mileage	17,993 Miles Warranted	Service history	None	Gears	6
Fuel Type	Hybrid Electric	MOT Due	07/04/2026	Doors	5
Colour	SILVER	CAP Clean	£16,050.00		
VIN	SJNTAAJ12U1090096	CAP Average	£14,700.00		

£100 ADDITIONAL FEE

### Tyres

NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	3.0mm
OSF	GOODYEAR	2.0mm
OSR	GOODYEAR	4.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image

No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Door nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door nsr  
Dented  
With Paint Damage



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Up To 50mm




8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint






9: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



10: Door osr  
Scratched  
Over 25mm Not Thru Paint



11: Door osf  
Scratched  
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK