



# VEHICLE INSPECTION REPORT

**GV70HXC**

## Peugeot 208 1.2 PureTech 100 Allure Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/12/2020	Keys	2	CAP Clean	£7,600.00
Year	2020	Service history	Yes	CAP Average	£6,700.00
Mileage	69,339 Miles Warranted	Service documents	Service Book	CAP Below	£5,775.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	RED	Last service date	13/09/2024	Gears	6
VIN	VR3UPHNKLT115657	Last service miles	63,950	Doors	5
Body Style	Hatchback	MOT Due	30/12/2025		

LAST SERVICE 13/9/24 @ 63950 MILES (4 SERVICE 1 MAIN DEALER) Intermittent rough idle engine wanting to stall

### Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5





3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Chipped  
1 To 5



5: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



6: Wheel nsr  
Scratched  
Over 50mm



7: Door nsf  
Chipped  
Edge Chip



8: Door nsf  
Chipped  
1 To 5



9: Wheel nsf  
Scratched  
Over 50mm



10: Bonnet  
Chipped  
1 To 5

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK