



VEHICLE INSPECTION REPORT

KU62FYS

Seat MII 1.0 Ecomotive 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/11/2012	Keys	2	CAP Clean	£2,375.00
Year	2012	Service history	Yes	CAP Average	£1,925.00
Mileage	61,640 Miles Warranted	Service documents	Service Book	CAP Below	£1,475.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	WHITE	Last service date	11/09/2024	Gears	5
VIN	VSSZZZAAZDD312630	Last service miles	57,904	Doors	5
Body Style	Hatchback	MOT Due	17/09/2025		

NEW CAMBELT FITTED 27/07/2022 @ 45766 MILES Last service 11/09/2024 @ 57904 miles (10 SERVICES 3 MAIN DEALER)

Tyres

NSF	BUDGET	4.0mm
NSR	YOKOHAMA	2.0mm
OSF	BUDGET	4.0mm
OSR	YOKOHAMA	2.0mm
Spare		

Features


- Rear wiper
- Front electric windows
- Drivers airbag
- Remote central locking
- Radio/CD
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Solid Paint
- Traction control
- Steel wheels
- Air conditioning
- ABS
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Scratched
UpTo 25mm Thru Paint




4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
2 Or Less UpTo 10mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Bonnet
Scratched
Over 25mm Thru Paint



10: Bumper Front
Chipped
Multiple Chips



11: Bumper Front
Scratched
Over 25mm Not Thru Paint



12: Wing osf
Rusted
UpTo 5mm



13: Door osf
Poor Previous Repair
Poor Paint



14: Door osr
Poor Previous Repair
Poor Paint



15: Qtr Panel osr
Poor Previous Repair
Paint Flake

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK