



VEHICLE INSPECTION REPORT

BL65WZS

Ford Fiesta 1.0 EcoBoost Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/02/2016	Keys	2	CAP Clean	£2,300.00
Year	2016	Service history	Yes	CAP Average	£1,900.00
Mileage	96,136 Miles Warranted	Service documents	Service Book	CAP Below	£1,450.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	BLACK	Last service date	15/03/2024	Gears	5
VIN	WF0DXXGAKDFT55235	Last service miles	84,427	Doors	5
Body Style	Hatchback	MOT Due	22/03/2026		

£65 ADDITIONAL FEE, LAST SERVICE 15-03-2024 @84427 MILES (3 SERVICES)
TYRE PRESSURE LIGHT ON

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	7.0mm
Spare		

Features


- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel nsf
Scratched
Over 50mm



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Qtr Panel osr
Chipped
1 To 5




6: Bumper Rear
Scratched
25 to 100mm Thru Paint




7: Tailgate
Scratched
UpTo 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Chipped
1 To 5



11: Wing nsf
Scratched
Over 25mm Not Thru Paint



12: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK