

VEHICLE INSPECTION REPORT

AO59USG

Toyota Auris 1.4 D-4D TR 5dr [6]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape.
		V5	TBC	· -	
Details					
Reg. date	14/11/2009	VIN	SB1KC56E10F059785	CAP Average	£1,050.00
Year	2009	Body Style	Hatchback	CAP Below	£625.00
Mileage	89,154 Miles Warranted	Keys	2	Gearbox	MANUAL
		MOT Due	26/06/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£1,425.00	Doors	5
Colour	SILVER			-	
Tyres					
NSF		FIRESTONE		4.0mm	
NSR		FIRESTONE		5.0mm	
OSF		FIRESTONE		4.0mm	
OSR		FIRESTONE		5.0mm	
Spare					

Features


- Rear wiper
 Air conditioning
- Rear headrests
- Passenger airbagAlloy wheels
- Radio/CD
- Climate control
- Metallic Paint
- · Central locking
- Body coloured bumpers
- Front electric windows
- ABS
- Remote central locking
- Electric door mirrors
- · Rear electric windows
- Drivers airbag
- Cloth seat trim

Photos






















Condition Check



Damage Photos



1: Bumper Rear Chipped 1 To 5



2: Door nsf Scratched UpTo 25mm Thru Paint



3: Door Mirror Assy nsf Scratched (Painted) Over 25mm Thru Paint



4: Wing nsf Dented Over 30mm



5: Bumper Front Poor Previous Repair Poor Paint



6: Bonnet Chipped Multiple Chips



7: A Post os Chipped 1 To 5



8: Wing osf Scratched Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average Average **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK